



IECEX Quality Assessment Report Summary

INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEx Scheme visit www.iecex.com

QAR Ref. No.:	DE/TUN/QAR09.0005/09	Page 1 of 1
QAR Free Ref. No.:	22 216 319478	Status: Issued
Details of change:	Re-Assessment	Date of issue: 2022-10-19
Site(s) audited:	SICK Engineering GmbH Bergener Ring 27 01458 Ottendorf-Okrilla Germany	Valid until: 2025-10-19 Audit date: 2022-07-22
Issuing ExCB:	TUN - TÜV NORD CERT GmbH	
Manufacturer:	SICK Engineering GmbH Bergener Ring 27 01457 Ottendorf-Okrilla	
Location of Manufacturer:	Germany	
Product information:	Devices of the environment and process technology	
Protection concept:	Flameproof enclosures "d" Increased safety "e" Intrinsic safety "i" Optical Radiation, type of protection "op is" Dust protection by enclosures "t" Equipment protection by type of protection "n" (nA)	
Related QARs:		
DE/TUN/QAR09.0005/00	DE/TUN/QAR09.0005/01	DE/TUN/QAR09.0005/02
DE/TUN/QAR09.0005/03	DE/TUN/QAR09.0005/04	DE/TUN/QAR09.0005/05
DE/TUN/QAR09.0005/06	DE/TUN/QAR09.0005/07	DE/TUN/QAR09.0005/08
Related Certificates (manual insertion)::		
Related Certificates (automatic linking)::		
Related Certificates for previous versions:		
IECEX BVS 19.0061X issue: 0	IECEX BVS 19.0062X issue: 0	IECEX BVS 19.0062X issue: 1
IECEX BVS 19.0062X issue: 2	IECEX BVS 20.0079X issue: 0	IECEX FTZU 15.0032X issue: 0
IECEX FTZU 15.0032X issue: 1	IECEX FTZU 15.0032X issue: 2	IECEX FTZU 16.0014 issue: 0
IECEX FTZU 21.0010X issue: 0	IECEX SIR 15.0053X issue: 0	IECEX SIR 15.0053X issue: 1
IECEX SIR 15.0053X issue: 2	IECEX SIR 16.0001X issue: 0	IECEX SIR 16.0001X issue: 1
IECEX SIR 16.0001X issue: 2	IECEX SIR 20.0021X issue: 0	IECEX SIR 20.0021X issue: 1
IECEX TUN 09.0015 issue: 0	IECEX TUN 09.0015X issue: 1	IECEX TUN 09.0016 issue: 0
IECEX TUN 09.0016X issue: 1	IECEX TUN 10.0023X issue: 0	IECEX TUN 10.0023X issue: 1
IECEX TUN 11.0001X issue: 0	IECEX TUN 11.0001X issue: 1	IECEX TUN 12.0020X issue: 0
IECEX TUN 12.0032X issue: 0		
Comments:	Product Quality Assurance Notification TÜV 09 ATEX 555405 Q	