



IECEX Quality Assessment Report Summary

INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEx Scheme visit www.iecex.com

QAR Ref. No.:	DE/TUN/QAR13.0008/10	Page 1 of 2	
QAR Free Ref. No.:	22 216 319477	Status: Issued	
Details of change:	Re-Assessment	Date of issue: 2022-11-09	
Site(s) audited:	SICK AG Gisela-Sick-Straße 1 79276 Reute Germany	Valid until: 2025-09-06	
	SICK AG Erwin-Sick-Str. 1 79183 Waldkirch Germany	Audit date: 2022-08-25	
	SICK AG Poppenbütteler Bogen 9b 22399 Hamburg Germany		
	SICK AG Rengoldshauser Straße 17a 88662 Überlingen Germany		
	SICK Kft Fő út 49 9184 Kunsziget Hungary		
	SICK AG Abrichstraße 4 with additional location Weißerlenstrasse 8 76108 Freiburg Germany		
Issuing ExCB:	TUN - TÜV NORD CERT GmbH		
Manufacturer:	SICK AG Erwin-Sick-Straße 1 79183 Waldkirch		
Location of Manufacturer:	Germany		
Product information:	Apparatus and equipment for measurement and control		
Protection concept:	Flameproof enclosures "d" Pressurized enclosures „p“ Increased safety “e” Intrinsic safety “i” Type of protection “n” Encapsulation “m” Optical radiation “op is” Dust protection by enclosures “t”		
Related QARs:			
	DE/TUN/QAR13.0008/00	DE/TUN/QAR13.0008/01	DE/TUN/QAR13.0008/02
	DE/TUN/QAR13.0008/03	DE/TUN/QAR13.0008/04	DE/TUN/QAR13.0008/05
	DE/TUN/QAR13.0008/06	DE/TUN/QAR13.0008/07	DE/TUN/QAR13.0008/08
	DE/TUN/QAR13.0008/09		

Related Certificates (manual insertion)::



IECEX Quality Assessment Report Summary

QAR Ref. No.: **DE/TUN/QAR13.0008/10**

Page 2 of 2

Related Certificates (automatic linking)::

Related Certificates for
previous versions:

IECEX BVS 13.0111X issue: 0
IECEX BVS 17.0032X issue: 0
IECEX BVS 19.0004X issue: 0
IECEX BVS 19.0005X issue: 1
IECEX EPS 11.0006X issue: 3
IECEX IBE 14.0024X issue: 0
IECEX IBE 14.0025X issue: 1
IECEX KIWA 20.0016X issue: 0
IECEX PTB 14.0031 issue: 0
IECEX TUN 14.0038 issue: 1

IECEX BVS 13.0111X issue: 1
IECEX BVS 17.0059X issue: 1
IECEX BVS 19.0004X issue: 1
IECEX BVS 19.0006X issue: 0
IECEX EPS 15.0016X issue: 0
IECEX IBE 14.0024X issue: 1
IECEX KIWA 20.0014X issue: 0
IECEX PTB 14.0030 issue: 0
IECEX PTB 14.0031 issue: 1
IECEX TUR 18.0067X issue: 0

IECEX BVS 13.0111X issue: 2
IECEX BVS 17.0060U issue: 1
IECEX BVS 19.0005X issue: 0
IECEX BVS 19.0006X issue: 1
IECEX EPS 15.0016X issue: 1
IECEX IBE 14.0025X issue: 0
IECEX KIWA 20.0015X issue: 0
IECEX PTB 14.0030 issue: 1
IECEX TUN 14.0038 issue: 0
IECEX TUR 20.0064X issue: 0

Comments: